FORM APPROVED Division of Health Care Facilities (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA COMPLETED **IDENTIFICATION NUMBER:** AND PLAN OF CORRECTION A. BUILDING: 02 - BOULEVARD TERRAACE NURSING HOME B. WING 04/12/2019 TN7502 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 1530 MIDDLE TENNESSEE BLVD **BOULEVARD TERRACE REHABILITATION AND** MURFREESBORO, TN 37130 PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE SUMMARY STATEMENT OF DEFICIENCIES (X4) ID (EACH CORRECTIVE ACTION SHOULD BE (EACH DEFICIENCY MUST BE PRECEDED BY FULL **PREFIX** PREFIX DATE CROSS-REFERENCED TO THE APPROPRIATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) {N 000} {N 000} Initial Comments Stories: 1 Construction Type: II No plans available on site Constructed: 1989 (Secure unit 2003) Sprinklered: Yes Census: 60 A Life Safety revisit survey was conducted on 04/12/19 for the previous deficiencies cited on 02/19/2019. The deficiencies have been corrected, and no new non compliance was found. The facility is in compliance with all regulations surveyed.

Division of Health Care Facilities LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Care Facilities STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY COMPLETED IDENTIFICATION NUMBER: AND PLAN OF CORRECTION A. BUILDING: 02 - BOULEVARD TERRAACE NURSING HOME B. WING 02/19/2019 TN7502 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 1530 MIDDLE TENNESSEE BLVD **BOULEVARD TERRACE REHABILITATION AND** MURFREESBORO, TN 37130 PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES (X5)(X4) ID (EACH CORRECTIVE ACTION SHOULD BE COMPLETE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX PRÉFIX DATE CROSS-REFERENCED TO THE APPROPRIATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) N 000 Initial Comments N 000 Stories: 1 Construction Type: II No plans available on site Constructed: 1989 (Secure unit 2003) Sprinklered: Yes Census: 60 A Life Safety Code Survey was conducted by the State of Tennessee Department of Health Division of Health Licensure and Regulations Office of Health Care Facilities on 02/19/2019. During this Life Safety Survey, Boulevard Terrace was found not in substantial compliance with the requirements of the Tennessee Rules and Regulations 1200-08-06, Standards for Nursing Homes, and National Fire Protection Association (NFPA) 101 Life Safety (2012 Edition). The requirements at 1200-080-06, Standards for Nursing Homes is NOT MET as evidenced by: \*\*\*\* All penetrations requiring fire stop shall be repaired in accordance with a tested and approved fire stop system meeting the requirements of the UL (Underwriters Laboratory) assembly to which the fire stop is being applied. The system used shall be recorded and documentation shall be maintained for the life of the installation. Fire stop systems used shall be made available to surveyors. N 831 N 831 N 831 1200-8-6-.08 (1) Building Standards (1) A nursing home shall construct, arrange, and 1200-8-6-.08(1) Building Standards maintain the condition of the physical plant and the overall nursing home environment in such a The facility will maintain the overall manner that the safety and well-being of the environment residents are assured.

Division of Health Care Facilities

STATE FORM

ABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Mayar

Mhimstritox GXQE21 3/7/20[9 If continuation sheet 1 of 2

ii soliiii osaloii biloot 1 or

Division of Health Care Facilities STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY **IDENTIFICATION NUMBER:** AND PLAN OF CORRECTION COMPLETED A. BUILDING: 02 - BOULEVARD TERRAACE NURSING HOME B. WING TN7502 02/19/2019 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 1530 MIDDLE TENNESSEE BLVD **BOULEVARD TERRACE REHABILITATION AND** MURFREESBORO, TN 37130 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE (X4) ID (EACH CORRECTIVE ACTION SHOULD BE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX PREFIX DATE CROSS-REFERENCED TO THE APPROPRIATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) N 831 N 831 Continued From page 1 1. The 2 unsealed beams going thru the wall and at the deck from the rehabilitation unit into the secure unit were sealed with 3M fire barrier by plant operations staff on This Rule is not met as evidenced by: Based on observations, the facility failed to 3/31/2019 maintain the overall environment. 2. Beams in other areas of the building were inspected by facility The finding included: and regional plant operation staff Observation on 02/19/2019 at 11:30 AM, revealed on 2/19/2019 for compliance. the fire/smoke rated masonry (seperating the rehabilitation from the secure unit) had 2 3. Plant Operations staff was inunsealed steel beams going through the wall, and serviced on 3/4/2019 regarding was unsealed at the deck. sealing of beams by administrator. NFPA 101, 8.3.5.1 (2012 Edition) Compliance will be monitored The maintenance director and regional plant during annual inspections. operations was present when this deficiency was 4. The Plant Operations or identified, and was later acknowledged by the administrator during the exit conference on Administrator will report findings 02/19/2019. of the audits to the QAPI committee for follow up and recommendations as needed for 3 months. The QAPI committee consist of Medical Director. Administrator, DON, Unit Managers, Resident Financial Coordinator, Human Resource, Medical Records, Social Services, Plant Operations, Activities and Dietary. 3/31/2019

GXQE21